

Hallberg Rassy 42

Year imm:	1990
Length:	12.93 mt
Max speed:	8.0 knots
Gross Tonnage:	24000.00
Draught:	2.00 mt
Flag:	

Year built:	1990
Width:	3.80 mt
Croc speed:	7.0 knots
Displacement:	12000 Kg
Maturity. Rina:	

Price

205 000 €

sold

Brief description

Fully equipped boat: radar, bow thruster, furling jib and mainsail, heating pilot etc.

Materials

Hull:	PFRV
Tuga:	sandwich balsa e ponte in TEAK

Blanket:	PFRV
----------	------

Plumbers

Tanks:	2
Material:	Not indicated
Autoclave:	You

Ability:	Not indicated
Boiler:	You 220/ motore
Water Maker:	No

Electric

Tension:	12/220
Batteries:	6

Charge batt.:	You
Ability:	600

Gen. 220: No	Power: Not indicated
Inverter: You	
Fuels and engines	
Motors: 1	Power: 62 HP D
Brand: Volvo Penta	Model: TDM22
Transmission: Line d ' axis	Moto hours: 860
Tanks: 1	Ability: 420 litres
Material: inox	Propeller: Not indicated
Review:	

Interior

Internal layout: standard mahogany furniture.
Two cabins and two bathrooms. Square with L-shaped sofa on the left, front sofa to starboard and folding table between the sofas. Guest area with hallway closets on the starboard side forward of square section, with shower toilet compartment on the left, double cabin with 2 bunk beds V convertible bed.
Owner's cabin aft with a single bed and a double to left to starboard, the starboard section armada left wide toilet with shower in separate compartment. New shaped spring mattresses for beds.
The kitchen has a double stainless steel sink, gas cooker 2 burners and oven served by 2 external compartment tanks, electric refrigerator with Danfoss compressor.
Covers for sofa upholstery.
Shaped pads for mattresses.
Egyptian cotton profiled sheets for beds.
hot/cold water shower with mixer at the Lazaretto; waste water tanks for both toilets

Armament

OUTDOOR SHOWER IN COCKPIT: hot and cold water, warm water, fridge, stove, HEATING with HOT AIR VENTS IN every room, 220 SOCKET well.
AUTOMATIC COURTESY LIGHTS IN EVERY WARDROBE, supplemental lights-SPOTLIGHTS DINETTE AREA, ADDITIONAL SOCKETS 220 IN ANY ENVIRONMENT including the bathrooms.
AUTOMATIC COURTESY LIGHTS IN EVERY WARDROBE, supplemental lights-SPOTLIGHTS DINETTE AREA, swim platform with footbridge
ADDITIONAL SOCKETS 220 IN ANY ENVIRONMENT including the bathrooms.

GREEN ALPS MARBLE-CLOSURE OF THE ENTIRE KITCHEN AREA INCLUDING COOKER WITH SINK AND FRIDGE.

LEATHER FINISH DINETTE (FULL BLOOM) COLOR VERDONE.

NEW CUSHIONS AND UPHOLSTERY FABRICS MAZZORATO CABINS.

OUTDOOR CUSHIONS COMPLETE COCKPIT SEATS AND BACKS IN CAPITONEE, WHITE WITH BLUE BUTTONS AND PROFILE.

STEERING WHEEL COVER, COVER COVER HATCH COVER WINCH COVER, COMPASS, AND BLUE RESCUE EQUIPMENT.
BOW THRUSTER (bow truster)
FURLING MAIN SAIL
FURLING JIB

Instrumentation

- Suunto compass on the binnacle;
- water/wind instruments Raymarine ST 60 WIND, TRIDATA, CH/WIND (2012);
- autopilot Autohelm ST-7000 with second unit to correspondence;
- GPS plotter Raymarine C80 colour in the cockpit;
- VHF Shipmate RS 8100 with Repeater in cockpit;
- Radar Furuno 1830 (1997);
- stereo 2 speakers with IPOD docking FUSION with square and 2 in cockpit;
- radar reflector;

- windex masthead;
- Gold-baro-station hygro

bow thruster Sleipner 7 hp;

- Generator.

Additional notes

Helix Max-prop 3 blade prop + new Commons to 3 fixed blades;

- slice tops mounted on the propeller;

1000W electric windlass;

- CQR anchor from 20 kg. with 60 m chain 8 mm;

The teak deck is made of solid rubber and counterbore perfect only thing missing some CAP as per photo.

- stock still with FX23 Fortress m. 15 chain and 40 m in height to yet;
- fixed splash with fabric extension and additional coverage for the entire cockpit;
- raft inflatable eurovinil for 8 people review performed in 2012;
- safety equipment in accordance with incl. 2 fire extinguishers;
- automatic fire extinguishing system in the engine compartment;
- some rubber rings and automatic safety collars;
- teak on the stern pulpit bracket for outboard motor;
- cockpit table mounted on the binnacle;
- tendon night for the hatches;
- Hood for cockpit table and binnacle;
- bimini awning above the original HR-boma;
- cushions wells fixable;
- teak seating corners of Stern pulpit;