

## Navigando S.r.I.

Venue: P.zza Milano nr 9 Lavagna (GE) Italy Tel: 348/2618615 - 0185/1908164 Fax: 0185/1908165

# Starkel Stag 50

•	
Year imm:	Year built:
1987	1986
	No. 10.
Length: 15.12 mt	Width: 3.78 mt
13.12 IIII	3.70 Hit
Max speed:	Croc speed:
9.0 knots	7.0 knots
Gross Tonnage:	Displacement:
0.00	<b>0</b> Kg
Draught:	Maturity. Rina:
<b>2.68</b> mt	2024
Flag:	
italiana	
Price	
79 000 €	
little negotiable	
nao nogotable	
Brief description	
Boat in good used condition.	
Excellent fast cruiser ULDB.	
Materials	
	<b>8</b> 1. 4. 4
Hull:	Blanket: <b>sandwich</b>
grp	Salidwich
Tuga:	
Plumbers	
Tanks:	Ability:
1	500 litres
Material:	Boiler:
inox	You 200/ motore
Autoclave:	Water Maker:
No	No
El	
Electric	
Tension:	Charge batt.:
12/24/220	You

Batteries:	Ability:	
3	300	
Gen. 220:	Power:	
No	Not indicated	
Inverter:		
No		
Fuels and engines		
Motors:	Power:	
1	73 HP D	
Brand:	Model:	
Nanni Mercedes	Not indicated	
Transmission:	Moto hours:	
	500	
Tanks:	Ability:	
1	160 litres	
Material:	Propeller:	
	Not indicated	
Review:		

#### Interior

Three cabins 3 bathrooms including one master with separate room others guest cabin passageway. electric toilets mounted 2021 C-shaped dinette with opposing sofa convertible into bed. Large TAvolo with butterfly opening and convertible into very comfortable double bed. Kitchenette with double sink cooker with burners and oven. Refrigerator with double opening. charting

#### Armament

Cutter rigging, RAnda on full batten trolleys, genoa 160% of 2021, foresail on dedicated forestay, non-structural steering wheels, jankee, Spinnaker with rigging, Gennaker with stocking. Rebuilt rigging 2021. Boiler, refrigerator, electricand manual bilge popmp. 10 winches. Cork cockpit and deckhouse. Plexi of portholes redone. Cockpit cushions. Sun awning, double dinette table replacing the original.

### Instrumentation

Raymarine tacticks wind station (2022) log, echo, autopilot, 2020 gps plotter, vhf.

#### Additional notes

Landing the engine and refitted in 2021, new rigging, Boat from boliniere and speed characteristics typical of these ULDBs. Very good state of preservation and maintenance.